



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

ENGINEERING CHANGE REQUEST

ECR 386

Date Opened:	4/11/22 1:29 PM	Requested By:	Drouin, Steven
Type:	Drawing/Pattern Change	Responsible Engineer:	Drouin, Steven
Priority:	Medium	Requester*:	McMachen, Lisa
Status:	Quality Disposition	DE Approver*:	Shepherd, David
Reason:		ECR Lead*:	Drouin, Steven
Expense:	0		
Target Date:			
Execution Date:			
ECR Approval No:			
RE (R&D):		**BRIEF DESCRIPTION**:	D169-841 cable cutter system
Status Note:		DESCRIPTION/ ADR CONTENT**:	This is a issue is with Leonardo and Dart not Labelling Leonardo part Numbers on DART Manufactured parts before leaving the Hawkesbury facility.

CUSTOMER APPROVALS

Customer	Customer Visible	Customer Approval Required	*	Customer Approved
----------	------------------	----------------------------	---	-------------------

PARTS

Part No	Rev	Part Status	Name	Type	Customer Part	Special Comments	Documents
D169-841-011		On hold	AW169 Cable Cutter System	Finished Good			
D169-841-013		On hold	AW169 Upper Cutter Deflector	Finished Good			
D169-841-015		On hold	AW169 Lower Cutter	Finished Good	D169-841-015		URF 16-692-(841).pdf

INVENTORY DISPOSITION

Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty	Qty Scheduled for Production
D169-841-011		0 Quarantine	0 *	0 *
D169-841-013		0 Quarantine	0 *	5 *
D169-841-015		1 Quarantine	0 *	6 *

EFFECTS

Effect Group	Effects
1. Quarantine?	Immediate quarantine required
2. ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required
3. ECR Lead Assessment - Status During ECR	UR - Full Under Review
5A. ECR Lead Assessment - MINOR Changes	Correction of drawing errors
7. Final Impacts	Paperwork Update, Parts Must Comply